## USEPA REGION I FACILITY INFORMATION

Inspector's Name: Don GRANT	FRP REGIONA	AL #:N/A			
Inspection Team Members: TOE CANZANO					
Type of Inspection: SPCC[X] FRP[] SPCC and FRP[] Follow-up Inspection[] Plan Review []					
Name of Facility: BROWNS YACHT YAK	2D				
Facility Address: 139 EAST MAIN S	· 77,				
City: GLOVCESTER County: ESSE	i	State: MA	Zip: 0/930		
	Longitude:	70.649	6 11		
Nearest "Waters of the U S.": ADJACONT TO AT	CANTIC (	DLEAN			
Facility Contact: PETER BENT	ONSE	Title: PRES	IDENT		
Facility Contact: 2.		Title:			
Telephone Number: 6 17 281-3200					
Name of Owner/Operator:					
Corporate Address:					
City: 5		State:	Zip:		
Corporate Contact:		Title:	*		
Telephone Numbers: 1. 2.					
Synopsis of business operations: BOAT REPAIR, MARINA W/ FUEL DOCK					
Facility is: [ ] Unattended [ ] Attended [ ] 8 hrs [ ] 24 hrs] [ ] Periodically [ ] Other (Specify)					
How many employees at this Facility? 15					
If unmanned, number of employees needed to operate the Facility?					

Revised: Feb 28, 2006

## FACILITY STORAGE INVENTORY

ITEM	TANK ID NUMBER	SHELL CAPACITY	PRODUCT	ITEM	TANK ID NUMBER	SHELL CAPACITY	PRODUCT
1.	* UST	6,000	GASOLINE	2.			
3	* UST	6,000	DIESEL	4.			
5.	AST	275	0FF1CE #2	6.			
7.		275	F/G TENT KELD	8.			,
9.		275 275 275	F/G- TENT	10.			8
11.		275	WASTE OLL	12.			
13.			NEW LUBES	14.			
15.				16.			
17.				18.			
19.				20.			
21.				22.			
23.				24.			
25.				26.			

Total Bulk Above Ground Storage:	1,760	gallons		
Total Bulk Below Ground Storage:	12,000	gallons 🗡	SPCC	EXEMPT
Total Oil-Filled Equipment Storage		gallons		
Total Facility Oil Storage Capacity:	13,760	_ gallons		

Revised: Feb 28, 2006
Page 2 of 5

SEE ATTA	HED MAP			
		data		
		RESPONSE		
				.*

OVE	ER	PAVE	DYARD	OR	DOWN	FLOOR	DRAINS	DIRECTLY
10	OC	EAN						
		3						

Revised: Feb 28, 2006

Memorandum of Unde	rstanding (check all appl	icable descriptions):	
Non-Transportation	Related	[ ] Transportation Rela	ited
[X] EPA	[] MMS	[ ] USCG	[ ] RSPA/OPS
[X] Onshore [] Off shore [] Prilling [] Production [] Refining [] In-plant processing [] Waste Treatment [] Storage [] Commercial [] Agriculture [] Industrial [] Public [] Load/Unloading [] Facility Piping	[ ] Drilling [ ] Production [ ] Storage	[ ] Vessel/shore transfer [ ] Oily ballast tanks [ ] Tank washings from vessels	[ ] Inline/ Breakout Tanks: (for continuous pipeline operation)
SPCC Part 112.1(b)	[ ] Producing [ ] Gathering  Storing	[ ] Processing [ ] Refining [ Transferring	Distributing Consuming oil/oil products
Facility Type: [] Bulk storage [] Gas Station /Convenience [] Petroleum Distributor	RESI Industrial [] Commercial [] Utilities [] Local Gov. [] State Gov. [] Federal (Non-Military)	[ ] Federal(Military) [ ] Air Taxi(Airline) [ ] Aircraft owner [ ] Auto Dealership [ ] Contractor [ ] Farm	[ ] Railroad [ ] Residential [ ] Trucking /Transport [ ] Trustee/Native American [ ] Other:

\_\_\_\_The Oil Pollution Prevention Regulations at 40 CFR Part 112 do not appear to be applicable to this facility.

✓ The Oil Pollution Prevention Regulations at 40 CFR Part 112 are applicable to this facility.

If your facility has been found to be in noncompliance with the provisions of 40 CFR Part 112, you are hereby required to submit as soon as possible, a statement detailing the actions taken by the facility to correct the deficiencies specified in the attached. If, in order to correct the deficiencies, your facility was required to prepare an SPCC plan, or amend an existing SPCC plan, you are also required to submit a copy of such new or revised plan. If completion of the plan is not feasible within thirty (30) days, you are hereby required to submit a detailed schedule of when the SPCC plan or revision thereof will be completed. The schedule should include the name and address of the registered professional engineer certifying the plan. If the plan calls for the construction of secondary containment at the facility, the schedule should include construction milestone dates. This information should be sent to the EPA inspector listed below at the following address:

Office of Environmental Stewardship
Mail Code: SEW
U.S. Environmental Protection Agency
New England Region
One Congress Street
Boston, MA 02114 - 2023

Revised: Feb 28, 2006

Please be advised that the facility's noncompliance with the Oil Pollution Prevention regulations at 40 CFR Part 112 constitutes a violation of the Clean Water Act for which both injunctive relief and penalties can be sought. Under the Clean Water Act, the facility is subject to penalties up to \$27,500 per day for violations occurring from January 31, 1997, through March 15, 2004, and up to \$32,500 per day for violations occurring after March 15, 2004.

EPA reserves its right to take an enforcement action pursuant to the Clean Water Act, including the right to seek penalties, for any violations detected at the above-referenced inspection. Although preparing and/or revising an SPCC plan and submitting it to EPA does not preclude EPA from seeking penalties for violations of the Clean Water Act, your prompt response towards coming into full compliance with the Oil Pollution Prevention regulations will be taken into account in determining EPA's enforcement response.

EPA Inspector Signature: Nonell a- Grant	Date:
EPA Inspector Printed Name: Donaco As GRAVT	Title: ENV. PROT. SPEC
I acknowledge having received an SPCC inspection by EPA on the	is date.
Company Contact Signature:	Date: July 3/ 2007
Company Contact Printed Name: Poster Box	Title: Pres.